

## **WS-505/506 INITIAL INSTALLATION NOTICE:**

On some Ducati 900 SS/CR models, it may be necessary to make a slight adjustment to the helmet holder wires. They are located on the bike – under the seat, just to the left and right of the pin lock. Upon the initial installation of the World Sport seat, check to see if there is a conflict with these wire forms. If so, flex them down slightly until the clearance is achieved. This will not affect the functionality of the holder wires.

Also, please note that on the Ducati 900SS/CR (and some SL) models, the rubber spacer on the underside of some factory original seat cowls may cause discoloration on the red or yellow vinyl. To prevent this, we recommend you cover the rubber spacer with some tape.

## **WS-505/506 INITIAL INSTALLATION NOTICE:**

On some Ducati 900 SS/CR models, it may be necessary to make a slight adjustment to the helmet holder wires. They are located on the bike – under the seat, just to the left and right of the pin lock. Upon the initial installation of the World Sport seat, check to see if there is a conflict with these wire forms. If so, flex them down slightly until the clearance is achieved. This will not affect the functionality of the holder wires.

Also, please note that on the Ducati 900SS/CR (and some SL) models, the rubber spacer on the underside of some factory original seat cowls may cause discoloration on the red or yellow vinyl. To prevent this, we recommend you cover the rubber spacer with some tape.

## **WS-505/506 INITIAL INSTALLATION NOTICE:**

On some Ducati 900 SS/CR models, it may be necessary to make a slight adjustment to the helmet holder wires. They are located on the bike – under the seat, just to the left and right of the pin lock. Upon the initial installation of the World Sport seat, check to see if there is a conflict with these wire forms. If so, flex them down slightly until the clearance is achieved. This will not affect the functionality of the holder wires.

Also, please note that on the Ducati 900SS/CR (and some SL) models, the rubber spacer on the underside of some factory original seat cowls may cause discoloration on the red or yellow vinyl. To prevent this, we recommend you cover the rubber spacer with some tape.